24" BANDSAW

MODEL G7211/G7212

PARTS LIST

COPYRIGHT ©1992 BY GRIZZLY INDUSTRIAL, INC.

WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.

REVISED AUGUST, 2000 PRINTED IN TAIWAN

DISCONTINUED MACHINE PARTS LIST DISCLAIMER

THESE PARTS REPRESENT THE LAST CONFIGURATION OF THE MACHINE BEFORE IT WAS DISCONTINUED. MACHINE CONFIGURATIONS MAY HAVE CHANGED AS PRODUCT IMPROVEMENTS WERE INCORPORATED. IF YOU OWN AN EARLIER VERSION OF THE MACHINE, THIS PARTS LIST MAY NOT EXACTLY DEPICT YOUR MACHINE. CONTACT CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS ABOUT PART DIFFERENCES. PREVIOUS PARTS LIST VERSIONS ARE NOT AVAILABLE ONLINE.

G7211 PARTS LIST

Ref#	Part#	Description
001	P7211001	BODY
002	P7211002	BEARING BASE
003	P6206	6206 BEARING
004	P7211004	SHAFT
005	PK27M	KEY 7 X 7 X 25
006	P7211006	HEX NUT ¾ X 16NF
007	P7211007	BEARING COVER
008	P7211008	WASHER ¾"
009	P7211009	PAN SCREW ¼ X ⅝"
010	P7211010	ADJUSTING SCREW
011	P7211011	SPRING WASHER ⅜"
012	P7211012	HEX SCREW ⅜ X1 ½"
013	P7211013	ADJUST WHEEL
014	P7211014	SET SCREW 5⁄16 X ⅜"
015	P7211015	WASHER ⅜"
016	P7211016	HEX SCREW ⅜ X 1"
017	P7211017	BUSH
017A	P7211017A	HEX NUT
018	P7211018	LOCK SCREW 5⁄16 X 3"
019	P7211019	UPPER WHEEL BASE
020	P7211020	BRACKET SHAFT
021	P7211021	SET SCREW 5⁄16 X ⅜"
022	P7211022	ADJUST BRACKET
023	P7211023	ADJUST SCREW
024	P7211024	ELEVATOR BRACKET
025	P7211025	SPRING
026	P7211026	GUIDE SPINDLE
026A	P7211026A	SPINDLE BUSHING
027	P7211027	UPPER WHEEL GUIDE BRACKET
028	P7211028	C-RING S-20
029	P7211029	LEVER SHAFT
030	P7211030	BUSH
031	P7211031	LOCKING SCREW
032	P7211032	UPPER ADJUST BRACKET
033	P7211033	C-RING S-25
034	P6205	BEARING 6205
035	P7211035	UPPER WHEEL BEARING BASE
036	P7211036	UPPER WHEEL SHAFT
037	P7211037	BLADE WHEEL
038	P7211038	RUBBER COATING
039	P7211039	WASHER ¾"
040	P7211040	HEX NUT ¾ X 16NF
041	P7211041	UPPER GUARD
042	P7211042	LOWER GUARD
043	P7211043	HEX SCREW ¼ X1 ¼"

Ref#	Part#	Description
044	P7211044	BRAKE WHEEL
045	PVB36	V-BELT B-36 5L360
046	P7211046	*SEE CATALOG*
047	P7211047	CAP SCREW ¼ X1 ¼"
048	P7211048	BRAKE BELT LOCKING
049	P7211049	BRAKE BELT
050	P7211050	HEX SCREW ¼ X ⅝"
051	P7211051	HEX NUT ¼ X ⅝"
052	P7211052	BRAKE SWITCH
053	P7211053	MOTOR PULLEY
054	PVB25	V-BELT B-255 L250
055	P7211055	INTERMEDIATE WHEEL
056	P7211056	C-RING S-20
057	P6204	BEARING 6204
058	P7211058	INTERMEDIATE WHEEL SHAFT
059	P7211059	WASHER ½"
059A	P7211059A	LOCK WASHER
060	P7211060	HEX NUT ½"
061	P7211061	MOTOR
062	P7211062	MOTOR MOUNTING PLATE
063	P7211063	HEX SCREW ⅜ X 2 ½"
064	P7211064	BRAKE PEDAL
065	P7211065	SPRING
066	P7211066	DUST CHUTE
067	P7211067	BUSH
068	P7211068	GUIDE RAIL
069	P7211069	CAP SCREW 5⁄16 X 2 ½"
070	P7211070	SET SCREW 5⁄16 X ½"
071	P7211071	RAIL COVER
072	P7211072	FENCE
073	P7211073	LOCKING KNOB
074	P7211074	WORKING TABLE
075	P7211075	INSERT
076	P7211076	SPRING PIN
077	P7211077	MITER GAUGE BAR
078	P7211078	POINTER
079	P7211079	PAN SCREW 3⁄16 X ¼"
080	P7211080	PIN
081	P7211081	MITER GAUGE
082	P7211082	GUIDE DISC
083	P7211083	LOCKING SCREW
084	P7211084	TABLE GAUGE BRACKET
085	P7211085	SPRING WASHER ⅜"
086	P7211086	HEX SCREW ⅜ X 1 ½"
087	P7211087	TRUNNION

Ref#	Part#	Description
088	P7211088	LOCKING HANDLE
089	P7211089	LOCKING HANDLE
090	P7211090	LOWER GUIDE BRACKET
091	P7211091	BLADE SUPPORT SHAFT
091B	P6202	BEARING
091C	P7211091C	GUIDE SHAFT
091D	P7211091D	SPACER
091E	P7211091E	C-RING S-15
092	P7211092	HEX SCREW
093	P7211093	CAP SCREW ¼ X ⅝"
094	P7211094	SET SCREW ¼ X ⅜"
095	P7211095	UPPER GUIDE BRACKET
096	P7211096	LOCKING SHAFT
097	P7211097	GUIDE WHEEL
098	P7211098	GUIDE BAR BRACKET
099	P7211099	BLADE GUARD
100	P7211100	BLADE INTER GUARD
101	P7211101	HEX SCREW ¼ X ⅝"
102	P7211102	GUIDE BAR
103	P7211103	ELEVATOR HAND WHEEL
104	P7211104	GEAR
105	P7211105	GUIDE BAR CASE BRACKET
106	P7211106	WASHER
107	P7211107	NUT ½"
108	P7211108	LOCK KNOB
109	P7211109	SCREW ¼ X ⅝"
110	P7211110	SCREW 3⁄16 X 1 ½"
111	P7211111	BRUSH
112	P7211112	WASHER 3⁄16"
113	P7211113	NUT 3⁄16-24 NC
114	P7211114	STRAIN RELIEF
115	P7211115	MOTOR CORD
116	P7211116	SWITCH ON/OFF
117	P7211117	SCREW
118	P7211118	POWER CORD
120	P7211120	SCREW
125	P7211125	LABEL

The parts list for the G7212 is identical except that Reference #61 Motor is a 7.5 H.P. horse-power, three-phase motor - G6249.

G7211/G7212 PARTS DIAGRAM



G7211/G7212 PARTS DIAGRAM