

# ***Grizzly*** ***Industrial, Inc.***®

## **WOOD LATHE WITH STAND**

### **MODEL G8691**

### **PARTS LIST**



COPYRIGHT © 2000 BY GRIZZLY INDUSTRIAL, INC.  
**WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE  
OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.**  
FEBRUARY, 2001. PRINTED IN CHINA.

#### **PARTS LIST DISCLAIMER**

THIS PARTS LIST AND DRAWINGS REPRESENT THE CONFIGURATION OF THE MACHINE AS IT IS CURRENTLY BEING SHIPPED. THE MACHINE CONFIGURATION CAN CHANGE AS PRODUCT IMPROVEMENTS ARE INCORPORATED. IF YOU OWN AN EARLIER VERSION OF THE MACHINE, THIS PARTS LIST MAY NOT DEPICT YOUR MACHINE EXACTLY. CONTACT CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS ABOUT PART DIFFERENCES. PREVIOUS PARTS LIST VERSIONS ARE NOT AVAILABLE ONLINE.



| Ref# | Part#    | Description              |
|------|----------|--------------------------|
| 001  | P8691001 | Motor                    |
| 002  | P8691002 | Shaft Pin                |
| 003  | P8691003 | Motor Pulley             |
| 004  | P8691004 | Phillips® Hd Scr M6 x 20 |
| 005  | P8691005 | Belt Cover               |
| 006  | P8691006 | Motor Mount Plate        |
| 007  | P8691007 | Hex Head Screw M8 x 16   |
| 008  | PW 01M   | Washer M8                |
| 009  | P8691009 | Hex Hd Scr M8 x 16       |
| 010  | P8691010 | Hex Hd Scr M6 x 12       |
| 011  | P8691011 | Stud M8 x 40             |
| 012  | P8691012 | Adjustment Plate         |
| 013  | P8691013 | Circuit Base             |
| 014  | P8691014 | Self Tapping Scr M3 x 8  |
| 015  | P8691015 | Label                    |
| 016  | P8691016 | Spindle                  |
| 017  | P8691017 | Shaft Pin                |
| 018  | P8691018 | Shaft Nut                |
| 019  | G2522    | M.T. #2 Spur Center      |
| 020  | P8691020 | Face Plate               |
| 021  | P8691021 | Ball Bearing             |
| 022  | P8691022 | Ball Bearing             |
| 023  | P8691023 | Internal Retaining Ring  |
| 024  | P8691024 | Shaft Pulley             |
| 025  | P8691025 | V-Belt                   |
| 026  | P8691026 | Tool Rest                |
| 027  | P8691027 | Hex Hd Scr M12 x 40      |
| 028  | P8691028 | Socket Setscrew M8 x 10  |
| 029  | P8691029 | Tool Rest Shaft          |
| 030  | P8691030 | Tool Rest Base           |
| 031  | P8691031 | Lever Shaft              |
| 032  | P8691032 | Lever Knob               |
| 033  | P8691033 | Tool Rest Tension Plate  |
| 034  | P8691034 | Lever Shaft              |
| 035  | P8691035 | Lever Knob               |
| 36A  | G1807    | M.T. #2 Live Center      |
| 039  | P8691039 | Tailstock                |
| 040  | P8691040 | Guide Screw              |
| 041  | P8691041 | Hex Hd Scr M24 x 3       |
| 042  | P8691042 | Tailstock Hand Wheel     |
| 043  | P8691043 | Socket Setscrew M6 x 10  |
| 044  | P8691044 | Hex Hd Scr M12 x 40      |
| 045  | PW06M    | Washer M12               |
| 046  | P8691046 | Tailstock Tension Plate  |
| 047  | P8691047 | Turning Knob             |
| 048  | P8691048 | Nut                      |
| 049  | P8691049 | Speed Switch             |
| 050  | G8992    | Switch                   |
| 051  | P8691051 | Fuse                     |

| Ref# | Part#      | Description                  |
|------|------------|------------------------------|
| 052  | P8691052   | Phillips® Hd Scr M6 x 12     |
| 053  | P8691053   | Switch Label                 |
| 054  | P8691054   | Switch Faceplate             |
| 055  | P8691055   | Bracket                      |
| 056  | P8691056   | Press Plate                  |
| 057  | P8691057   | Rubber Sheath                |
| 058  | P8691058   | Phillips® Hd Scr M4 x 10     |
| 059  | PN03M      | Nut M8                       |
| 060  | PWRCRD110L | Power Cord 110v, Long W/Plug |
| 061  | P8691061   | Lathe Bed                    |
| 062  | P8691062   | Electronic Circuit           |
| 063  | P8691063   | Phillips® Hd Scr M6 x 12     |
| 064  | PW 01M     | Washer M8                    |
| 065  | P8691065   | Hex Hd Scr M8 x 16           |
| 066  | P8691066   | Electric Label               |
| 067  | P8691067   | Directional Label            |
| 068  | P8691068   | Cover                        |
| 069  | P8691069   | Wrench                       |
| 070  | PN03M      | Nut M8                       |