


SECTION 10: PARTS

Motor



T30943 Motor Parts List

REF	PART #	DESCRIPTION
1	PT30943001	INT RETAINING RING 19MM
2	PT30943002	SPACER
3	PT30943003	SPACER (PLASTIC)
4	PT30943004	SPRING SEAT
5	PT30943005	COMPRESSION SPRING
6	PT30943006	SPINDLE
7	PT30943007	SET SCREW M10-1.5 X 12
8	PT30943008	TAP SCREW M5 X 55
9	PT30943009	SPACER
10	PT30943010	SPINDLE HOUSING SEAL
11	PT30943011	BALL BEARING 6904-2RS
12	PT30943012	GEAR 47T
13	PT30943013	EXT RETAINING RING 16MM
14	PT30943014	GEAR COVER
15	PT30943015	INT RETAINING RING 42MM
16	PT30943016	BALL BEARING 6905-2RS
17	PT30943017	GEAR BOX
18	PT30943018	SPACER
19	PT30943019	CAP SCREW M5-.8 X 20
20	PT30943020	BALL BEARING 608VV
21	PT30943021	GEARED SHAFT
22	PT30943022	WOODRUFF KEY 3 X 9

REF	PART #	DESCRIPTION
23	PT30943023	ARMATURE GEAR 8T
24	PT30943024	PRESSBOARD WASHER 25MM
25	PT30943025	BALL BEARING 6000-DU
26	PT30943026	ARMATURE
26A	PT30943026A	MOTOR ASSEMBLY
27	PT30943027	BALL BEARING 608DI
28	PT30943028	MOUNTING PLATE
29	PT30943029	TAP SCREW M4 X 65
30	PT30943030	LOCK WASHER 4MM
31	PT30943031	GASKET
32	PT30943032	STATOR
33	PT30943033	MOTOR COVER
35	PT30943035	CARBON BRUSH COVER
36	PT30943036	CARBON BRUSH
37	PT30943037	SET SCREW M5-.8 X 5
38	PT30943038	BRUSH HOLDER
39	PT30943039	MOTOR COVER CAP
40	PT30943040	STRAIN RELIEF TYPE-3 M12 X 1.5
41	PT30943041	TAP SCREW M5 X 25
43	PT30943043	MOTOR CORD 5W 16"
43-1	PT30943043-1	MOTOR CORD COVER
44	PT30943044	LEVEL

T30944 Motor Parts List

REF	PART #	DESCRIPTION
1	PT30944001	INT RETAINING RING 19MM
2	PT30944002	SPACER
3	PT30944003	SPACER (PLASTIC)
4	PT30944004	SPRING SEAT
5	PT30944005	COMPRESSION SPRING
6	PT30944006	SPINDLE
7	PT30944007	SET SCREW M10-1.5 X 12
8	PT30944008	TAP SCREW M5 X 65
9	PT30944009	SPACER
10	PT30944010	SPINDLE HOUSING SEAL
11	PT30944011	BALL BEARING 6904-2RS
12	PT30944012	GEAR 47T
13	PT30944013	EXT RETAINING RING 16MM
14	PT30944014	GEAR COVER
15	PT30944015	INT RETAINING RING 42MM
16	PT30944016	BALL BEARING 6905-2RS
17	PT30944017	GEAR BOX
18	PT30944018	SPACER
19	PT30944019	CAP SCREW M5-.8 X 20
20	PT30944020	BALL BEARING 608VV
21	PT30944021	GEARED SHAFT
22	PT30944022	WOODRUFF KEY 3 X 9

REF	PART #	DESCRIPTION
23	PT30944023	ARMATURE GEAR 5T
24	PT30944024	PRESSBOARD WASHER 25MM
25	PT30944025	BALL BEARING 6000-DU
26	PT30944026	ARMATURE
26A	PT30944026A	MOTOR ASSEMBLY
27	PT30944027	BALL BEARING 608DI
28	PT30944028	MOUNTING PLATE
29	PT30944029	TAP SCREW M4 X 70
30	PT30944030	LOCK WASHER 4MM
31	PT30944031	GASKET
32	PT30944032	STATOR
33	PT30944033	MOTOR COVER
35	PT30944035	CARBON BRUSH COVER
36	PT30944036	CARBON BRUSH
37	PT30944037	SET SCREW M5-.8 X 6
38	PT30944038	BRUSH HOLDER
39	PT30944039	MOTOR COVER CAP
40	PT30944040	STRAIN RELIEF TYPE-3 M12 X 1.5
41	PT30944041	TAP SCREW M5 X 45
42	PT30944042	TAP SCREW M5 X 30
43	PT30944043	MOTOR CORD 5W
43-1	PT30944043-1	MOTOR CORD COVER


Parts breakdown provided for reference only. Not all parts shown are available for purchase.

Model T30943/T30944 (Mfd. Since 10/19)

BUY PARTS ONLINE AT GRIZZLY.COM!
Scan QR code to visit our Parts Store.



Stand



Stand Parts List

REF	PART #	DESCRIPTION
101	PT30943101	COOLANT BOTTLE CAP
102	PT30943102	COOLANT BOTTLE
103	PT30943103	VALVE ASSEMBLY
104	PT30943104	COOLANT HOSE
105	PT30943105	ELBOW FITTING 90 DEG
106	PT30943106	CAP SCREW M6-1 X 16
107	PT30943107	SLIDING CARRIAGE
108	PT30943108	RACK
109	PT30943109	HEX NUT M5-.8
110	PT30943110	FLAT HD SCR M3-.5 X 6 BRASS
111	PT30943111	ROLL PIN 3 X 8
112	PT30943112	GUIDE, LEFT (BRASS)
113	PT30943113	FRAME
114	PT30943114	GIB
115	PT30943115	STRAIN RELIEF TYPE-3 M12 X 1.5
116	PT30943116	SET SCREW M5-.8 X 20
117	PT30943117	GUIDE, RIGHT (BRASS)
118	PT30943118	E-CLIP 15MM
119	PT30943119	FLAT WASHER 17MM SS
120	PT30943120	BALL BEARING 6903ZZ
121	PT30943121	EXT RETAINING RING 18MM
122	PT30943122	GEAR 44T
123	PT30943123	SLEEVE
124	PT30943124	PINION SHAFT
125	PT30943125	MACHINE KEY 5 X 5 X 14 RE
126	PT30943126	HOLLOW HANDLE 30 X 122
127	PT30943127	SHOULDER BOLT M10-1.5 X 28, 10 X 82
128	PT30943128	HANDLE CAP
130	PT30943130	GASKET
131	PT30943131	EXT TOOTH WASHER 4MM
132	PT30943132	SPADE TERMINAL

REF	PART #	DESCRIPTION
133	PT30943133	PHLP HD SCR M4-.7 X 8
134	PT30943134	POWER CORD 14G 3W 84" 5-15P
135	PT30943135	STRAIN RELIEF M14-2 SPIRAL-FLEX
136	PT30943136	TAP SCREW M3 X 8
137	PT30943137	PLASTIC COVER
138	PT30943138	POTENTIOMETER HUNGYUN B503
139	PT30943139	SWITCH PANEL
140	PT30943140	PHLP HD SCR M3-.5 X 6 SS
141	PT30943141	MOTOR ON/OFF SWITCH DKLD LDZ04-2B 14A
142	PT30943142	POTENTIOMETER DIAL
143	PT30943143	MAGNET ON/OFF SWITCH CQC KCD5 10A 250V
144	PT30943144	FUSE HOLDER
144-1	PT30943144-1	FUSE MF527 10A 250V
145	PT30943145	CIRCUIT BOARD CHENG XIANG CXXLB19-28
146	PT30943146	CIRCUIT BOARD SUPPORT
147	PT30943147	TAP SCREW M4 X 10
148	PT30943148	PHLP HD SCR M3-.5 X 8
149	PT30943149	CAP SCREW M6-1 X 55
150	PT30943150	MAGNET (T30943)
150	PT30944150	MAGNET (T30944)
151	PT30943151	CAP SCREW M6-1 X 20
152	PT30943152	REAR PANEL (T30943)
152	PT30944152	REAR PANEL (T30944)
153	PT30943153	PLASTIC STORAGE CASE (T30943)
153	PT30944153	PLASTIC STORAGE CASE (T30944)
154	PT30943154	NYLON STRAP 5'
155	PT30943155	DRILL CHUCK 1/16"-1/2" 1/2-20
156	PT30943156	DRILL CHUCK KEY
157	PT30943157	WELDON 3/4" TO 1/2" ADAPTER
158	PT30943158	HEX WRENCH SET 4, 5, 6, 8MM



Labels & Cosmetics



201



202



203

205



202

204



REF PART #	DESCRIPTION
201 PT30943201	MACHINE ID LABEL W/QR CODE (T30943)
201 PT30944201	MACHINE ID LABEL W/QR CODE (T30944)
202 PT30943202	ELECTRICITY LABEL

REF PART #	DESCRIPTION
203 PT30943203	GRIZZLY PRO LABEL
204 PT30943204	STORAGE CASE LABEL
205 PT30943205	WARNING LABEL

WARNING

Safety labels help reduce the risk of serious injury caused by machine hazards. If any label comes off or becomes unreadable, the owner of this machine **MUST** replace it in the original location before resuming operations. For replacements, contact (800) 523-4777 or www.grizzly.com.

