
SECTION 7: PARTS

We do our best to stock replacement parts when possible, but we cannot guarantee that all parts shown are available for purchase. Call **(800)** 523-4777 or visit www.grizzly.com/parts to check for availability.

Main




Main Parts List

REF	PART#	DESCRIPTION
1	PT32957001	TABLE
2	PT32957002	CUTTER BAR
3	PT32957003	HOLD DOWN
4	PT32957004	SIDE PANEL (RIGHT)
5	PT32957005	SIDE PANEL (LEFT)
6	PT32957006	EXTENSION ARM
7	PT32957007	HEX BOLT M12-1.75 X 30
8	PT32957008	COMPRESSION SPRING 3 X 22 X 165
9	PT32957009	STUD-UDE M12-1.75 X 220, 25, 45
10	PT32957010	ACORN NUT M12-1.75
11	PT32957011	HEX BOLT M12-1.75 X 80
12	PT32957012	FLAT WASHER 12MM
13	PT32957013	BLADE GUARD
14	PT32957014	PHLP HD SCR M6-1 X 15
15	PT32957015	90-DEG STOP
16	PT32957016	TABLE SCALE
17	PT32957017	HEX BOLT M8-1.25 X 25
18	PT32957018	HEX BOLT M10-1.5 X 60
19	PT32957019	HEX BOLT M10-1.5 X 50
20	PT32957020	FLAT WASHER 10MM
21	PT32957021	HEX BOLT M16-2 X 120
22	PT32957022	FLAT WASHER 16MM
23	PT32957023	HEX NUT M16-2
24	PT32957024	UPPER BLADE
25	PT32957025	LOWER BLADE
26	PT32957026	CAP SCREW M10-1.5 X 45
27	PT32957027	CAP SCREW M10-1.5 X 50
28	PT32957028	FLAT WASHER 10MM
29	PT32957029	FLAT WASHER 10MM
31	PT32957031	GIB
32	PT32957032	CAP SCREW M10-1.5 X 45
33	PT32957033	HEX NUT M10-1.5
34	PT32957034	BLADE BOW ROD
35	PT32957035	FLAT WASHER 14MM
36	PT32957036	HEX NUT M14-2
37	PT32957037	BOW BOLT M16-2 X 60
38	PT32957038	HEX NUT M12-1.75
39	PT32957039	FLAT WASHER 16MM
40	PT32957040	HEX BOLT M10-1.5 X 40

REF	PART #	DESCRIPTION
41	PT32957041	COMPRESSION SPRING 8 X 46 X 275
42	PT32957042	SPRING CAP
43	PT32957043	PIVOT BLOCK
44	PT32957044	PIVOT BRACKET
45	PT32957045	STUD-UDE M16-2 X 320, 2, 16
46	PT32957046	FLAT WASHER 16MM
47	PT32957047	HEX NUT M16-2
48	PT32957048	SPRING MOUNTING BRACKET
49	PT32957049	HEX BOLT M10-1.5 X 25
50	PT32957050	HEX NUT M16-2
51	PT32957051	CLEVIS PIN 12 X 88MM
52	PT32957052	CLEVIS PIN 12 X 45MM
53	PT32957053	HINGE PIN
54	PT32957054	FOOT PEDAL ASSEMBLY
55	PT32957055	STUD-DE M16-2 X 1480, 60
56	PT32957056	CLEVIS PIN 20 X 36MM
57	PT32957057	HEX BOLT M12-1.75 X 25
58	PT32957058	HEX BOLT M10-1.5 X 25
59	PT32957059	REAR WORK STOP
60	PT32957060	REAR WORK STOP MOUNT
61	PT32957061	MICRO-ADJUSTMENT BLOCK
62	PT32957062	KNOB M10-1.5, D35, ROUND KD
63	PT32957063	STUD-FT M10-1.5 X 90
64	PT32957064	HEX BOLT M10-1.5 X 30
65	PT32957065	KNOB BOLT M8-1.25 X 25, 6-LOBE, D35
66	PT32957066	REAR WORK STOP ADJUSTMENT BLOCK
67	PT32957067	CONNECTING STUD BRACKET
68	PT32957068	HEX BOLT M10-1.5 X 20
69	PT32957069	SUPPORT ROD
70	PT32957070	HEX NUT M16-2
71	PT32957071	FRONT WORK STOP
72	PT32957072	FLAT WASHER 12MM
73	PT32957073	T-BOLT M12-1.75 X 45
74	PT32957074	WING NUT M12-1.75
75	PT32957075	BEVEL GAUGE
76	PT32957076	COTTER PIN M3 X 50 STANDARD
77	PT32957077	FLAT WASHER 6MM
78	PT32957078	SUPPORT ROD SCALE

Labels & Cosmetics



101	PT32957101	MANUAL/EYE INJURY LABEL
102	PT32957102	MODEL NUMBER LABEL
103	PT32957103	AMPUTATION/LACERATION LABEL
104	PT32957104	TOUCH-UP PAINT, CAUTION YELLOW

REF PART # DESCRIPTION

105	PT32957105	DO NOT REMOVE GUARD LABEL
106	PT32957106	TOUCH-UP PAINT, GRIZZLY GREEN
107	PT32957107	MACHINE ID LABEL
108	PT32957108	OBLONG NAMEPLATE SMALL

AWARNING

Safety labels help reduce the risk of serious injury caused by machine hazards. If any label comes off or becomes unreadable, the owner of this machine MUST replace it in the original location before resuming operations. For replacements, contact (800) 523-4777 or www.grizzly.com.

