


G0497 Parts Breakdown



G0497 Parts List

REF	PART #	DESCRIPTION
1A	P0497001A	MAIN HAMMER FRAME-N/S 1/07
2	P0497002	SUPPORT BRACKET
3	P0497003	BRACE
4	P0497004	END COVER
5	P0497005	UPPER HAMMER CLAMP
6	P0497006	LOWER HAMMER CLAMP
8	PR21M	INT RETAINING RING 35MM
9A	P0497009A	ANVIL BASE-N/S 1/07
10	P0497010	ANVIL HEIGHT SCREW 1-8 x 11
11	P0497011	LOWER ANVIL
11-1	PSS07	SET SCREW 1/4-20 x 1/2
12	P0497012	COMBO JAM NUT 1-8 / 1/2-12
12-1	P0497012-1	LOCK HANDLE 1/2-12 X 5/16
13	P0497013	PNEUMATIC HAMMER
13-1	P0497013-1	HAMMER HEAD
13-2	P0497013-2	HAMMER HEAD FACING
14	P0497014	SOLENOID VALVE MOUNT PLATE
15	P0497015	SWITCH PLATE
16	P0497016	STRAIN RELIEF 1/2"
17	P0497017	SOLENOID VALVE CORD
18	P0497018	FOOT SWITCH CORD
19	P0497019	POWER CORD W/5-15 PLUG
20	P0497020	CONNECTOR TUBE
21	P0497021	ELBOW 1/4" NPT
22	P0497022	90° MALE CONNECTOR
23	P0497023	MALE CONNECTOR

REF	PART #	DESCRIPTION
24	P0497024	HOSE CLAMP
25	P0497025	FLEXIBLE HOSE 5/16" x 9-1/16"
26	P0497026	FOOT SWITCH
27	P0497027	CORRUGATED PLASTIC TUBE
28	P0497028	SOLENOID VALVE
29	P0497029	AIR CONTROL ASSEMBLY
29-1	P0497029-1	FILTER/REGULATOR UNIT
29-2	P0497029-2	LUBRICATOR UNIT
30	P0497030	HANDWHEEL
30-1	PSS02	SET SCREW 5/16-18 X 3/8
31	PSB06	CAP SCREW 1/4-20 X 1
32	PSB04	CAP SCREW 1/4-20 X 1/2
33	PSB05	CAP SCREW 1/4-20 X 3/4
34	PSBS20	BUTTON HD CAP SCR 1/4-20 X 1/2
35	PN07	HEX NUT 10-24
36	PLW02	LOCK WASHER 1/4
37	PFS03M	FLANGE SCREW M5-.8 X 6
38	PTLW02M	EXT TOOTH WASHER 5MM
39	PS06	PHLP HD SCR 10-24 X 3/8
40	P0497040	COMBO LABEL
41	P0497041	CRUSHING HAZARD LABEL
42	P0497042	EXPLOSION HAZARD LABEL
43	P0497043	MACHINE ID LABEL
44	P0497044	FLEXIBLE HOSE 5/16" x 13"
45	PAW05M	HEX WRENCH 5MM

WARNING

Safety labels warn about machine hazards and ways to prevent injury. The owner of this machine MUST maintain the original location and readability of the labels on the machine. If any label is removed or becomes unreadable, REPLACE that label before using the machine again. Contact Grizzly at (800) 523-4777 or www.grizzly.com to order new labels.

COPYRIGHT © JUNE, 2006 BY GRIZZLY INDUSTRIAL, INC. REVISED JANUARY, 2007 (BL)
**WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE
 OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.**
 #JK8281 PRINTED IN TAIWAN