


SECTION 9: PARTS

Main Parts Breakdown



Please Note: We do our best to stock replacement parts whenever possible, but we cannot guarantee that all parts shown here are available for purchase. Call (800) 523-4777 or visit our online parts store at www.grizzly.com to check for availability.



Main Parts List

REF	PART #	DESCRIPTION
1	P0540001	ECCENTRIC HAND LEVER
2	P0540002	ALIGNMENT PIN 8 X 43
3	P0540003	COLUMN M16-2 X 20
4	P0540004	LOCK HANDLE M10-1.5 X 25
5	P0540005	HOLD-DOWN CLAMP ARM
6	P0540006	PRESS PLATE
8	P0540008	FENCE
9	PS03M	PHLP HD SCR M6-1 X 8
10	P0540010	BLOCK RING 14MM
11	P0540011	PRESS ROD
12	P0540012	COMPRESSION SPRING .5 X 18 X 55
13	PR02M	EXT RETAINING RING 14MM
14	P0540014	WORK TABLE
15	P0540015	CONNECTING SEAT
16	P0540016	STOP ROD
17	P0540017	X-AXIS SHAFT
18	PB08M	HEX BOLT M6-1 X 20
19	PCAP50M	CAP SCREW M5-.8 X 10
20	P0540020	COVER
21	P0540021	Y-AXIS SHAFT
22	PCAP14M	CAP SCREW M8-1.25 X 20
23	P0540023	TABLE SUPPORT
24V2	P0540024V2	PLATE 12.3MM HOLE V2.01.12
25V2	P0540025V2	ELEVATION HANDWHEEL SHAFT V2.01.12
26	P0540026	ELEVATION HANDWHEEL 125 X 12MM
27	P0540027	HANDWHEEL HANDLE M8-1.25 X 63
28	PCAP01M	CAP SCREW M6-1 X 16
29	P0540029	KNOB M12- 1.75
30	P0540030	HANDLE M12-1.75 X 25
31	PCAP06M	CAP SCREW M6-1 X 25
32	PCAP40M	CAP SCREW M8-1.25 X 35
33	P0540033	L-BRACKET
34	P0540034	VERTICAL LEADSCREW
35	P0540035	LEADSCREW PLATE
36	PN02M	HEX NUT M10-1.5
37	PSS10M	SET SCREW M10-1.5 X 20
38	P0540038	LEADSCREW BLOCK
39	P51100	THRUST BEARING 51100
40	P0540040	GEAR
41	PRP39M	ROLL PIN 4 X 20
42	P0540042	COVER
43	P0540043	Z-AXIS SHAFT

REF	PART #	DESCRIPTION
44	P0540044	TABLE MOUNTING PLATE
45	P0540045	STUD-UDE M12-1.75 X 19, M10-1.5 X 12, 137
46	PN03M	HEX NUT M8-1.25
47	PSS03M	SET SCREW M6-1 X 8
48	P0540A12	MOTOR 3/4HP 110V 1-PH
48-1	P0540048-1	SWITCH
48-2	P0540048-2	WIRING BOX COVER
48-3	P0540048-3	CENTRIFUGAL SWITCH
48-4	P0540048-4	FAN
48-5	P0540048-5	FAN COVER
49	PB07M	HEX BOLT M8-1.25 X 25
50	PW01M	FLAT WASHER 8MM
51	P0540051	MOTOR PLATE
52	PCAP61M	CAP SCREW M10-1.5 X 20
53	PB140M	HEX BOLT M12-1.75 X 70
54	PN09M	HEX NUT M12-1.75
55	PB31M	HEX BOLT M10-1.5 X 40
56	PB23M	HEX BOLT M10-1.5 X 100
57	PW04M	FLAT WASHER 10MM
58	P0540058	STAND
59	P0540059	S CAPACITOR 12M 400V 1-1/4 X 2-3/4
60	P0540060	STAND CROSSBRACE
61	PCAP13M	CAP SCREW M8-1.25 X 30
62	PLW06M	LOCK WASHER 10MM
63	PLW04M	LOCK WASHER 8MM
64	PLW03M	LOCK WASHER 6MM
65	PW03M	FLAT WASHER 6MM
66	PB07M	HEX BOLT M8-1.25 X 25
67	PR39M	EXT RETAINING RING 8MM
68	P0540068	LEG
69	P0540069	CHUCK 3-16MM JT33
70	P0540070	CHUCK GUARD
71	P0540071	CAPACITOR COVER
72	PR03M	EXT RETAINING RING 12MM
73	PK48M	KEY 4 X 4 X 20
74	PCAP50M	CAP SCREW M5-.8 X 10
75	PW02M	FLAT WASHER 5MM
76	P0540076	MACHINE ID LABEL
77	PLABEL-11A	SAFETY GLASSES LABEL
78	PPAINT-1	GRIZZLY GREEN TOUCH-UP PAINT
79	P0540075	BLACK TOUCH-UP PAINT

