


# SECTION 9: PARTS

## Base Breakdown



# Base Parts List

REF	PART #	DESCRIPTION
1	P0717001	STAND
1-1	P0717001-1	STRAIN RELIEF
1-2	P0717001-2	POWER CORD 14G 3W 100" 6-15
1-3	PB125M	HEX BOLT M12-1.75 X 65
1-4	PN09M	HEX NUT M12-1.75
2	P0717002	HOSE 1 X 12"
3	P0717003	HOSE CLAMP 35MM
4	P0717004	COOLANT PUMP ASSEMBLY
5	PTH001M	TRUSS HD SCR M6-1 X 16
6	PLW03M	LOCK WASHER 6MM
7	P0717007	HOSE 5/16" X 51"
7-1	P0717007-1	HOSE CLAMP 14MM
7-2	P0717007-2	PUSH-ON HOSE FITTING 3/8 NPT-5/16"
9	P0717009	COOLANT PUMP COVER PANEL
9-1	PTH002M	TRUSS HD SCR M6-1 X 10
10	P0717010	CHIP TRAY
10-1	P0717010-1	KNOB 1/4-20 X 3/8"
11	P0717011	SAW BASE
11-1	PN02M	HEX NUT M10-1.5
11-2	PB01M	HEX BOLT M10-1.5 X 30
12	PB26M	HEX BOLT M8-1.25 X 30
13	PW01M	FLAT WASHER 8MM
14	PLW04M	LOCK WASHER 8MM
15	PN03M	HEX NUT M8-1.25
16	P0717016	WORK STOP BRACKET
17	P0717017	WORK STOP ROD
18	P0717018	KNOB 3/8-16 X 1.25
19	P0717019	WORK STOP

REF	PART #	DESCRIPTION
20	P0717020	LOCK HANDLE M12-1.25 X 24
21	P0717021	HANDWHEEL ASSEMBLY 5.5"
21-1	PSS02	SET SCREW 5/16-18 X 3/8
22	P0717022	LEAD SCREW BLOCK
23	PB26M	HEX BOLT M8-1.25 X 30
23-1	PLW04M	LOCK WASHER 8MM
23-2	PW01M	FLAT WASHER 8MM
24-1	P0717024-1	LEADSCREW
24-2	PK34M	KEY 5 X 5 X 20
25-1	P0717025-1	LEADSCREW NUT
25-2	PCAP13M	CAP SCREW M8-1.25 X 30
25-3	PLW04M	LOCK WASHER 8MM
26-1	P0717026-1	SLIDE BRACKET
26-2	PSS03M	SET SCREW M6-1 X 8
27-1	P0717027-1	WISE RACK
28-1	P0717028-1	WISE RACK PAWL
29-1	P0717029-1	WISE RACK PIN
30	P0717030	BUSHING CV 25 X 15MM
30-1	P0717030-1	SPACER
31	P0717031	TORSION SPRING
32	P0717032	PIVOT SHAFT
32-1	P0717032-1	PIVOT END CAP
32-2	P0717032-2	HOLLOW HEX BOLT M12-1.75 X 20
32-3	P0717032-3	GREASE FITTING STRAIGHT 1/16"
33	P0717033	PIVOT BRACKET
33-1	PSS13M	SET SCREW M10-1.5 X 12
34	PN09M	HEX NUT M12-1.75




# Base Parts List (continued)

REF	PART #	DESCRIPTION
35	PW06M	FLAT WASHER 12MM
36	PB35M	HEX BOLT M12-1.75 X 40
37	P0717037	TORSION SPRING SHAFT
38	PR10M	EXT RETAINING RING 22MM
39	PB26M	HEX BOLT M8-1.25 X 30
39-1	PW01M	FLAT WASHER 8MM
40	P0717040	MOTOR TILT PLATE
40-1	PN03M	HEX NUT M8-1.25
41	P0717041	LIMIT SWITCH PLATE
42	PW01M	FLAT WASHER 8MM
42-1	PLW04M	LOCK WASHER 8MM
43	PB09M	HEX BOLT M8-1.25 X 20
44	PB02M	HEX BOLT M6-1 X 12
45	P0717045	DOWNFEED LIMIT SWITCH
47	P0717047	HYDRAULIC CYLINDER MAIN PIN
48	PR09M	EXT RETAINING RING 20MM
49	PR11M	EXT RETAINING RING 25MM
50	PB35M	HEX BOLT M12-1.75 X 40
51	P0717051	HYDRAULIC CYLINDER ASSEMBLY
52	P0717052	HYDRAULIC CYLINDER TOP PIN
52-1	P0717052-1	COTTER PIN #2 X 1"
53	P0717053	HYDRAULIC MOUNTING PLATE
53-1	PLW06M	LOCK WASHER 10MM
53-2	PB01M	HEX BOLT M10-1.5 X 30
54	PB33M	HEX BOLT M12-1.75 X 50
55	PW06M	FLAT WASHER 12MM
56	P0717056	LOCK PLATE
57	PN06	HEX NUT 1/2-13

REF	PART #	DESCRIPTION
58	P0717058	SPRING BRACKET
58-1	PB26M	HEX BOLT M8-1.25 X 30
58-2	PW01M	FLAT WASHER 8MM
58-3	PLW04M	LOCK WASHER 8MM
58-4	PN03M	HEX NUT M8-1.25
59	P0717059	SPRING EYE BOLT 1/2-12 X 8
60	P0717060	EXTENSION SPRING
61	P0717061	ANGLE SCALE
61-1	PRIV013M	STEEL FLUTED RIVET 2.5 X 4MM
62	PB35M	HEX BOLT M12-1.75 X 40
63	P0717063	DOCK WASHER 12MM
63-1	PLW05M	LOCK WASHER 12MM
64	P0717064	WISE JAW-OUTER
65	PB33M	HEX BOLT M12-1.75 X 50
66	P0717066	PIVOT WASHER 12MM
66-1	PLW05M	LOCK WASHER 12MM
67	P0717067	WISE JAW-INNER
68	PB35M	HEX BOLT M12-1.75 X 40
69	PCAP07M	CAP SCREW M6-1 X 30
69-1	PLW03M	LOCK WASHER 6MM
69-2	PW03M	FLAT WASHER 6MM
70	P0717070	ELECTRICAL PANEL COVER
70-1	P0717070-1	DOOR HINGE PIN
71	P0717071	FUSE BLOCK
72	P0717072	CONTACTOR NHD C12D 110V
72-1	P0717072	CONTACTOR NHD C12D 110V
73	P0717073	TRANSFORMER GDM 100VA
74	P0717074	TERMINAL BAR 15P



# Saw Bow Breakdown



# Saw Bow Parts List

REF	PART #	DESCRIPTION
7	P0717007	HOSE 5/16" X 51"
7-1	P0717007-1	HOSE CLAMP 14MM
40	P0717040	MOTOR TILT PLATE
75	P0717075	HANDLE
76	PTH001M	TRUSS HD SCR M6-1 X 16
77	PB02M	HEX BOLT M6-1 X 12
77-1	PLW03M	LOCK WASHER 6MM
77-2	PW03M	FLAT WASHER 6MM
78	P0717078	WIRE BRUSH GUARD
79	P0717079	UPPER BLADE WHEEL COVER
80	P0717080	LOWER BLADE WHEEL COVER
82	P0717082	DRIVE WHEEL SPACER
83	P0717083	DRIVE WHEEL WASHER
84	P0717084	DRIVE WHEEL
85	P0717085	BLADE 119-1/2L X 1-1/16W VP TPI
86	PB49M	HEX BOLT M12-1.75 X 20
87	PCAP50M	CAP SCREW M5-.8 X 10
88	P0717088	FILTER SCREEN
89	PB75M	HEX BOLT M12-1.75 X 35
89-1	PLW05M	LOCK WASHER 12MM
90	P0717090	LOCK KNOB 1/4-20 X 10
91	P0717091	SAW BOW SUPPORT
91-1	PLW06M	LOCK WASHER 10MM
91-2	PCAP72M	CAP SCREW M10-1.5 X 30
92	P0717092	SAW BOW
92-1	PSS13M	SET SCREW M10-1.5 X 12
94	P0717094	GEAR BOX ASSEMBLY
94-1	PK62M	KEY 7 X 7 X 45
95	PK66M	KEY 7 X 7 X 55
96	P0717096	PULLEY COVER
96-1	P0717096-1	LOCK KNOB 1/4-20 X 1/2
97	P0717097	GEAR BOX PULLEY
98	PVA39	V-BELT A39
99	P0717099	MOTOR PULLEY
99-1	PSS16M	SET SCREW M8-1.25 X 10
100	PB03M	HEX BOLT M8-1.25 X 16
100-1	PW01M	FLAT WASHER 8MM
100-2	PLW04M	LOCK WASHER 8MM
102	P0717102	SUPPORT SHAFT
102-1	PR08M	EXT RETAINING RING 19MM
103	PB75M	HEX BOLT M12-1.75 X 35
104	P0717104	MOTOR MOUNT BRACKET
104-1	PW06M	FLAT WASHER 12MM
104-2	PN06	HEX NUT 1/2-13

REF	PART #	DESCRIPTION
107	PB07M	HEX BOLT M8-1.25 X 25
108	PW01M	FLAT WASHER 8MM
108-1	PLW04M	LOCK WASHER 8MM
109	PB118M	HEX BOLT M8-1.25 X 45
109-1	PW01M	FLAT WASHER 8MM
110	P0717110	MOTOR MOUNT PLATE
111	P0717111	MOTOR 1-1/2 HP 110/220V 50/60HZ 1PH
111-1	PCS001	CENT SWITCH 5/8-1725
111-2	PCP003	CONTACT PLATE 1" X 2.5" EXT
111-3	PC400S	S CAPACITOR 400M 125V 1-3/4 X 3-3/8
111-4	PC040F	R CAPACITOR 40M 250V 1-3/8 X 2-3/8
111-5	P0717111-5	JUNCTION BOX
111-6	P0717111-6	CAPACITOR COVER
111-7	P0717111-7	FAN
111-8	P0717111-8	FAN COVER
111-9	P6203ZZ	BALL BEARING 6203ZZ
111-10	P6205ZZ	BALL BEARING 6205ZZ
112	PW01M	FLAT WASHER 8MM
112-1	PLW04M	LOCK WASHER 8MM
113	PN03M	HEX NUT M8-1.25
114	PK110M	KEY 7 X 7 X 12
116	PCAP14M	CAP SCREW M8-1.25 X 20
118	P608ZZ	BALL BEARING 608ZZ
118-1	PLW04M	LOCK WASHER 8MM
119	PB49M	HEX BOLT M12-1.75 X 20
120	PW06M	FLAT WASHER 12MM
121	P6205Z	BALL BEARING 6205Z
122	P0717122	IDLER WHEEL
123	P0717123	BLADE GUARD
123-1	PB03M	HEX BOLT M8-1.25 X 16
123-2	PW01M	FLAT WASHER 8MM
123-3	PLW04M	LOCK WASHER 8MM
124	P0717124	LEFT GUIDE BRACKET
124-1	PSS06M	SET SCREW M8-1.25 X 16
124-2	P0717124-2	NOZZLE
124-3	P0717124-3	NOZZLE SUPPORT
124-4	PLW03M	LOCK WASHER 6MM
124-5	PB02M	HEX BOLT M6-1 X 12
125	P0717125	SPACER 8 X 25MM
126	P6201ZZ	BALL BEARING 6201ZZ
127	P0717127	ECCENTRIC SLEEVE
127-1	P0717127-1	SLEEVE
128	PLW04M	LOCK WASHER 8MM
129	PCAP45M	CAP SCREW M8-1.25 X 45




# Saw Bow Parts List (continued)

REF	PART #	DESCRIPTION
130	PCAP07M	CAP SCREW M6-1 X 30
130-1	PLW03M	LOCK WASHER 6MM
130-2	PW03M	FLAT WASHER 6MM
131	P0717131	TUNGSTEN CARBIDE BLADE GUIDE
132	PB126M	HEX BOLT M8-1.25 X 40
133	PLW04M	LOCK WASHER 8MM
133-1	PW01M	FLAT WASHER 8MM
134	P0717134	ADJUSTABLE BRACKET
135	P0717135	SCALE
135-1	PRIV013M	STEEL FLUTED RIVET 2.5 X 4MM
136	PCAP64M	CAP SCREW M10-1.5 X 25
137	P0717137	SLIDE
138	P0717138	LEFT BLADE BRACKET
140	PB31M	HEX BOLT M10-1.5 X 40
140-1	PW04M	FLAT WASHER 10MM
141	P0717141	BLOCK
142	P0717142	LOCK KNOB 3/8-16 X 2
143	PSS16M	SET SCREW M8-1.25 X 10
144	P0717144	RIGHT BLADE BRACKET
145	PB02M	HEX BOLT M6-1 X 12
145-1	PLW03M	LOCK WASHER 6MM
146	PW03M	FLAT WASHER 6MM
147	P0717147	WIRE BRUSH
148	P0717148	BUSHING
149	P0717149	RIGHT GUIDE BRACKET
150	P0717150	BRUSH BRACKET
151	PB02M	HEX BOLT M6-1 X 12
152	PLW03M	LOCK WASHER 6MM
153	PW03M	FLAT WASHER 6MM
155	PN09M	HEX NUT M12-1.75
155-1	PB27M	HEX BOLT M12-1.75 X 30
155-2	PLW05M	LOCK WASHER 12MM
155-3	PW06M	FLAT WASHER 12MM
156	P0717156	SAW BOW STOP M12-1.75 X 50
157	P0717157	BLADE GUARD
158	P0717158	KNOB 1/4-20 X 3/8"
159	P0717159	HOSE 8 X 700MM
160	P0717160	ADJUSTING VALVE
160-1	P0717160-1	HOSE 8 X 320MM
160-2	P0717160-2	HOSE CLAMP 14MM
160-3	P0717160-3	VALVE BRACKET
160-4	PLW03M	LOCK WASHER 6MM

REF	PART #	DESCRIPTION
160-5	PB02M	HEX BOLT M6-1 X 12
161	P0717161	POWER INDICATOR LIGHT TEND
162	P0717162	START SWITCH TEND
163	P0717163	EMER STOP SWITCH KEDU HY57B
164	P0717164	PUMP SWITCH TEND
165	P0717165	SPEED CONTROL VALVE
166	P0717166	CONNECTION TUBE
166-1	P0717166-1	HOSE 5/16 X 15-3/4"
166-2	P0717166-2	HOSE 5/16 X 37"
168	P0717168	CONTROL BOX
169	P0717169	CONTROL PANEL
169-1	P0717169-1	HYRAULIC MICRO-ADJUST VALVE
169-2	P0717169-2	ON/OFF SWITCH
170	PS05M	PHLP HD SCR M5-.8 X 8
172	P0717172	HANDLE M12-1.75 X 30
173	PN09M	HEX NUT M12-1.75
174	PSS08M	SET SCREW M4-.7 X 5
174-1	P0717174-1	HINGE PIN
175	PS09M	PHLP HD SCR M5-.8 X 10
176	P0717176	INDICATOR SCALE
177	P0717177	SLIDE BRACKET
178	P0717178	TENSION SHAFT
179	PK20M	KEY 5 X 5 X 15
180	P0717180	HANDWHEEL
181	P0717181	CONICAL SPRING 22 X 45 X 6MM
182	P0717182	SPACER 22MM
183	P0717183	TENSION INDICATOR
184	P51104	THRUST BEARING 51104
187	P0717187	BLADE WHEEL GUIDE
188	PSS02	SET SCREW 5/16-18 X 3/8
189	P0717189	EXTENSION CYLINDER
190	P0717190	BLADE WHEEL SHAFT
191	PN13M	HEX NUT M16-2
191-1	PSS03M	SET SCREW M6-1 X 8
192	PCAP14M	CAP SCREW M8-1.25 X 20
193	PCAP129M	CAP SCREW M12-1.75 X 20
193-1	P0717193-1	AXLE WASHER
194	P0717194	GIB
195	P0717195	WHEEL ALIGNMENT BOLT M16-2 X 30
196	PB34M	HEX BOLT M10-1.5 X 60
197	PLW06M	LOCK WASHER 10MM



# Labels



REF	PART #	DESCRIPTION
201	PLABEL-11C	SAFETY GLASSES LABEL HL
202	PLABEL-12A	READ MANUAL LABEL VL
203	P0717203	MACHINE ID LABEL
204	G8589	GRIZZLY NAMEPLATE-LARGE
205	P0717205	MODEL NUMBER LABEL
206	PLABEL-50B	BIOHAZARD LABEL HL

REF	PART #	DESCRIPTION
207	PLABEL-63	DISCONNECT 220V LABEL VL
208	PPAINT-1	GRIZZLY GREEN TOUCHUP PAINT
209	PPAINT-11	GRIZZLY PUTTY TOUCHUP PAINT
210	PLABEL-19A	NO HANDS/BLADE LABEL VL
211	PLABEL-63	DISCONNECT 220V LABEL VL

## **!WARNING**

Safety labels help reduce the risk of serious injury caused by machine hazards. If any label comes off or becomes unreadable, the owner of this machine **MUST** replace it in the original location before resuming operations. For replacements, contact (800) 523-4777 or [www.grizzly.com](http://www.grizzly.com).

