



12" SLIP ROLL

MODEL G7148

PARTS LIST




COPYRIGHT © OCTOBER, 2001 BY GRIZZLY INDUSTRIAL, INC.

**WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE
OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.
PRINTED IN CHINA**

PARTS LIST DISCLAIMER

THIS PARTS LIST AND DRAWINGS REPRESENT THE CONFIGURATION OF THE MACHINE AS IT IS CURRENTLY BEING SHIPPED. THE MACHINE CONFIGURATION CAN CHANGE AS PRODUCT IMPROVEMENTS ARE INCORPORATED. IF YOU OWN AN EARLIER VERSION OF THE MACHINE, THIS PARTS LIST MAY NOT DEPICT YOUR MACHINE EXACTLY. CONTACT CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS ABOUT PART DIFFERENCES. PREVIOUS PARTS LIST VERSIONS ARE NOT AVAILABLE ONLINE.



REF	PART #	DESCRIPTION
01	P7148001	Adjustment Screw
02	P7148002	Grease Cup
03	P7148003	Rotating Support
04	P7148004	Adjustment Knob
05	P7148005	Left Stand
06	P7148006	Bushing
07	P7148007	Flat Key 4 x 8
08	P7148008	Rear Movable Shaft
09	P7148009	Handle Shaft
10	P7148010	Right Stand
11	P7148011	Release Rod
12	PW03M	Flat Washer 6mm
14	PS11M	Screw M6-1 x 16

REF	PART #	DESCRIPTION
15	P7148015	Bushing
16	P7148016	Gear
17	P7148017	Fixed Shaft
18	P7148018	Front Movable Shaft
19A	P7148019A	Handle Assembly
23	P7148023	Pin
24	P7148024	Adjustment Knob
25	P7148025	Base
26	PW04M	Flat Washer 10mm
27	PLW06M	Lock Washer 10mm
28	PB047M	Hex Bolt M10-1.25 x 20
29	PSS02M	Setscrew M6-1 x 6