



12" DOUBLE DISC SANDER

MODEL G8793

PARTS LIST



COPYRIGHT ©2000 BY GRIZZLY INDUSTRIAL, INC.


**WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE
OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.**

JUNE, 2000 PRINTED IN TAIWAN

PARTS LIST DISCLAIMER

THIS PARTS LIST AND DRAWINGS REPRESENT THE CONFIGURATION OF THE MACHINE AS IT IS CURRENTLY BEING SHIPPED. THE MACHINE CONFIGURATION CAN CHANGE AS PRODUCT IMPROVEMENTS ARE INCORPORATED. IF YOU OWN AN EARLIER VERSION OF THE MACHINE, THIS PARTS LIST MAY NOT DEPICT YOUR MACHINE EXACTLY. CONTACT CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS ABOUT PART DIFFERENCES. PREVIOUS PARTS LIST VERSIONS ARE NOT AVAILABLE ONLINE.

G8793 DISC SANDER PARTS DIAGRAM



G8793 DISC SANDER PARTS LIST

REF# PART# DESCRIPTION

001	P8793001	BASE
002	P8793002	DISC HOUSING
003	P8793003	DISC
004	P8793004	DUST PORT
005	P8793005	DISC TABLE
006	P8793006	MOTOR ASSEMBLY
007	P8793007	MOTOR SUPPORT
008	P8793008	BUSHING, POINTER
010	P8793010	SHAFT
011	P8793011	NUT
012	P8793012	STAND
013	P8793013	TRUNNION, FRONT
014	P8793014	TRUNNION, REAR
015	P8793015	DISC GUARD
016	P8793016	POINTER
017	P8793017	TRUNNION ARC
018	P8793018	SCALE, FRONT TRUNNION
019	P8793019	SCALE, REAR TRUNNION
020	P8793020	ROTATION ARROW
021	PSB08	CAP SCREW $\frac{5}{16}$ -18 X $1\frac{1}{2}$ "
022	PW07	FLAT WASHER $\frac{5}{16}$ "
023	PN02	HEX NUT $\frac{5}{16}$ -18
024	PB19	HEX BOLT $\frac{1}{4}$ -20 X $\frac{1}{2}$ "
025	P8793025	PIN 5 X 15
026	PB13	HEX BOLT $\frac{1}{4}$ -20 X $1\frac{1}{4}$ "
027	PW01	FLAT WASHER $\frac{1}{2}$ "
028	PSS17	SET SCREW $\frac{5}{16}$ -18 X $\frac{5}{16}$ "

REF# PART# DESCRIPTION

029	P8793029	SWITCH
030	P8793030	PHLP HD SCR $\frac{3}{16}$ -24 X $\frac{3}{4}$ "
031	P8793031	PHLP HD SCR $\frac{3}{16}$ -24 X $\frac{1}{4}$ "
033	PK23M	KEY 5 X 5 X 25
034	PS04	PHLP HD SCR $\frac{1}{4}$ -20 X $\frac{1}{2}$ "
035	PS07	PHLP HD SCR $\frac{1}{4}$ -20 X $\frac{3}{8}$ "
036	P8793036	WASHER $\frac{1}{4}$ "
037	PSB07	CAP SCREW $\frac{5}{16}$ -18 X $\frac{3}{4}$ "
038	PB18	HEX BOLT $\frac{3}{8}$ -16 X 1"
039	PW02	FLAT WASHER $\frac{3}{8}$ "
040	PWRCRD110S	POWER CORD 110V, SHORT
041	PB09	HEX BOLT $\frac{5}{16}$ -18 X $\frac{1}{2}$ "
042	P8793042	SANDING DISC
047	PWRCRD110L	POWER CORD 110V, LONG W/PLUG
048	P8793048	STRAIN RELIEF
049	P8793049	STAR KNOB
050	PRP18M	ROLL PIN 4 X 12
053	PW07	FLAT WASHER $\frac{5}{16}$ "
054	PW02M	FLAT WASHER 5MM
055	P8793055	PHLP HD SCR $\frac{3}{16}$ -24 X $\frac{3}{8}$ "
060	P8793060	KNOB, MITER GAUGE
061	P8793061	$\frac{1}{4}$ " WASHER
062	P8793062	MITER GAUGE BODY
063	P8793063	PHLP HD SCR $\frac{3}{16}$ -24 X $\frac{3}{8}$ "
064	P8793064	POINTER
065	P8793001	MITER BAR
066	P8793066	STRAIN RELIEF