


Replacement Parts & Labels



REF	PART #	DESCRIPTION
1	PH8154001	GAS INLET TUBE
2	PH8154002	COLLET BODY
3	PH8154003	GAS NOZZLE #5
4	PH8154004	GAS NOZZLE #6
5	PH8154005	GAS NOZZLE #7
6	PH8154006	LONG COLLET BACKCAP
7	PH8154007	SMALL COLLET BACKCAP
8	PH8154008	COLLET 1.6MM
9	PH8154009	COLLET 1.8MM

REF	PART #	DESCRIPTION
10	PH8154010	COLLET 2MM
11	PH8154011	TIG TORCH & CABLE ASSEMBLY
12	PH8154012	WORK CLAMP & CABLE
13	PH8154013	ELECTRODE CLAMP & CABLE
14	PH8154014	FOOT REMOTE CONTROL
15	PLABEL-14	ELECTRICITY LABEL
16	PLABEL-12	READ MANUAL LABEL
17	PH8154017	WELDER ID LABEL
18	PH8154018	SHOCK WARNING LABEL

WARNING

Safety labels warn about machine hazards and ways to prevent injury. The owner of this welder **MUST** maintain the original location and readability of the labels on the welder. If any label is removed or becomes unreadable, **REPLACE** that label before using the welder again. Contact Grizzly at (800) 523-4777 or www.grizzly.com to order new labels.

