


SECTION 9: PARTS

We do our best to stock replacement parts when possible, but we cannot guarantee that all parts shown are available for purchase. Call **(800) 523-4777** or visit **www.grizzly.com/parts** to check for availability.

Main




Main Parts List

REF	PART #	DESCRIPTION
1	PT33127001	FLAT WASHER 10MM
2	PT33127002	HEX BOLT M10-1.5 X 30
3	PT33127003	BASE
4	PT33127004	FLAT HD CAP SCR M6-1 X 12
6	PT33127006	FENCE
7	PT33127007	FENCE ROD
8	PT33127008	FENCE COLLAR
9	PT33127009	COMPRESSION SPRING 2 X 33 X 80MM
10	PT33127010	MICRO-ADJUSTMENT BRACKET
11	PT33127011	KNOB BOLT M8-1.25 X 65, 4-LOBE, D40
12	PT33127012	CAP SCREW M8-1.25 X 20
13	PT33127013	SET SCREW M5-.8 X 8
14	PT33127014	GUIDE BLOCK
15	PT33127015	ADJUSTABLE HANDLE M8-1.25 X 25, 60L
17	PT33127017	HOLD-DOWN BRACKET
18	PT33127018	HOLD-DOWN ROD
20	PT33127020	CHUCK ACCESS COVER, PLASTIC
21	PT33127021	HEX NUT M12-1.75
22	PT33127022	FLAT WASHER 12MM
23	PT33127023	COMPRESSION SPRING 2 X 25 X 28MM
24	PT33127024	FLAT WASHER 20MM
25	PT33127025	TOOL RACK
26	PT33127026	CAP SCREW M6-1 X 12
27	PT33127027	POWER CORD 18G 3W 72" 5-15P
28	PT33127028	HAND GRIP
29V2	PT33127029V2	MOTOR 1/2HP 120V 1-PH V2.05.24
29V2-1	PT33127029V2-1	MOTOR FAN COVER
29V2-2	PT33127029V2-2	BALL BEARING 6202ZZ REAR
29V2-3	PT33127029V2-3	BALL BEARING 6203ZZ FRONT
29V2-4	PT33127029V2-4	MOTOR FAN
29V2-6	PT33127029V2-6	R CAPACITOR 24M 250V 1-3/8 X 2-1/2
30	PT33127030	HEX BOLT M10-1.5 X 25
31	PT33127031	LOCK WASHER 10MM
32	PT33127032	STEP PLATE
33	PT33127033	HAND LEVER, 450L
34	PT33127034	GEAR 34T
35	PT33127035	ROLL PIN 8 X 35
36	PT33127036	HUB
37	PT33127037	PLASTIC COVER
38	PT33127038	COMPRESSION SPRING 2 X 19 X 28MM
39	PT33127039	SHOULDER SCREW M10-1.5 40, 26 X 40

REF	PART #	DESCRIPTION
40	PT33127040	HAND LEVER CLUTCH
41	PT33127041	RACK COLUMN
42	PT33127042	COLUMN
43	PT33127043	DEPTH LOCK COLLAR
44	PT33127044	KNOB BOLT M8-1.25 X 15, 4-LOBE, D40
45	PT33127045	TABLE
46	PT33127046	PHLP HD SCR M8-1.25 X 20
48	PT33127048	BUSHING 3/4"
49	PT33127049	DRILL CHUCK B16 1.5-13MM
49-1	PT33127049-1	DRILL CHUCK KEY 1/4" SE 12T SD-1/2"
50	PT33127050	CAP SCREW M8-1.25 X 45
51	PT33127051	CAP SCREW M6-1 X 20
52	PT33127052	SHAFT
53	PT33127053	HEADSTOCK
54	PT33127054	CAP SCREW M8-1.25 X 25
55	PT33127055	FLAT WASHER 8MM
56	PT33127056	FENDER WASHER 6MM
57	PT33127057	MOTOR JUNCTION BOX
58	PT33127058	PHLP HD SCR M3-.5 X 14
59	PT33127059	SWITCH PLATE
60	PT33127060	PHLP HD SCR M4-.7 X 12
61	PT33127061	CAP SCREW M6-1 X 16
63	PT33127063	GAS SPRING 38MM
63-1	PT33127063-1	BALL STUD M8-1.25, 15MM
65V2	PT33127065V2	CIRCUIT BREAKER KUOYUH 88 4A V2.05.24
66	PT33127066	CHUCK GUARD
68	PT33127068	HEX NUT M8-1.25
70	PT33127070	STRAIN RELIEF TYPE 3 M16-2
71	PT33127071	LOCK WASHER 6MM
73	PT33127073	LOCK WASHER 8MM
74	PT33127074	PADDLE SWITCH KEDU HY18
75	PT33127075	HEX WRENCH 6MM
77	PT33127077	FLAT WASHER 6MM
78	PT33127078	ROLL PIN 5 X 35
79	PT33127079	HEX WRENCH 5MM
80	PT33127080	HEX WRENCH 3MM
81	PT33127081	MORTISING CHISEL 1/2"
82	PT33127082	MORTISING CHISEL 3/8"
83	PT33127083	MORTISING CHISEL 1/4"
84	PT33127084	DRILL CHUCK ARBOR MT#2 X B16



Labels & Cosmetics



REF	PART #	DESCRIPTION
101	PT33127101	ELECTRICITY LABEL
102	PT33127102	EYE LUNG HAZARD LABEL
103	PT33127103	READ MANUAL LABEL

REF	PART #	DESCRIPTION
104	PT33127104	GRIZZLY GREEN TOUCH-UP PAINT
105V2	PT33127105V2	MACHINE ID LABEL V2.05.24
106V2	PT33127106V2	MOTOR LABEL V2.05.24

WARNING

Safety labels help reduce the risk of serious injury caused by machine hazards. If any label comes off or becomes unreadable, the owner of this machine **MUST** replace it in the original location before resuming operations. For replacements, contact (800) 523-4777 or www.grizzly.com.

