


T33905 Parts Breakdown & List



REF	PART #	DESCRIPTION
1	PT33905001	HEX BOLT 5/16-18 X 1
2	PT33905002	FLAT WASHER 5/16
3	PT33905003	TOP BRACE (SHORT)
4	PT33905004	TOP BRACE (LONG)
5	PT33905005	LEG
6	PT33905006	HEX NUT 5/16-18

REF	PART #	DESCRIPTION
7	PT33905007	BOTTOM BRACE (SHORT)
8	PT33905008	BOTTOM BRACE (LONG)
11	PT33905011	CARRIAGE BOLT 5/16-18 X 1/2
12	PT33905012	ADJUSTABLE LEG EXTENSION
13	PT33905013	COMBO WARNING LABEL
14	PT33905014	GRIZZLY.COM LABEL

WARNING

Safety labels help reduce the risk of serious injury caused by machine hazards. If any label comes off or becomes unreadable, the owner of this machine **MUST** replace it in the original location before resuming operations. For replacements, contact (800) 523-4777 or www.grizzly.com.

